SAMPLE · Pre-written illustrative fixture

This is a pre-written illustrative fixture, not an automated AI inference.

Property Documentation Draft

Preliminary Severity: Major

Sample: the illustration suggests interior water exposure at a visible waterline. The cause, duration, and concealed damage are unverified.

VISIBLE OBSERVATIONS

- An illustrative waterline is shown across an interior wall.
- Silt-like residue is suggested near the lower wall.
- No electrical, structural, or attic condition is visible in this sample.

POTENTIAL CONCERNS & HAZARDS

- A photo cannot establish whether electrical systems or structural components are safe.
- Moisture may support mold growth in concealed spaces, but mold is not confirmed by this sample.
- Contaminated floodwater can present health risks; avoid unprotected contact.

RECOMMENDED NEXT STEPS

- Avoid entering areas with standing water, visible electrical damage, or unstable ceilings.
- Photograph the waterline and affected contents from a safe location.
- Contact a qualified inspector and the property owner or insurer before cleanup or repairs.
- Keep a dated record of discarded or damaged items.

LIMITATIONS & SCOPE

- This is a synthetic illustration, not a photograph of a real property.
- The visible waterline does not establish the water source, category, or full scope of damage.
- Pre-written illustrative sample, not live AI analysis of an uploaded image.
- Not an official FEMA classification, coverage or eligibility determination, or repair quote.
- Provisional documentation only; consult qualified professionals before decisions.

Document ID: `sample-fort-myers-flood`

Generated: Nov 2, 2026, 11:52 AM