



LM1 PORTABLE CALIBRATION TARGET

v1.0.0 - 6 x 6 checkerboard - 25 mm squares



Print at 100% / Actual size. Do not use Fit to page.

Place the board flat beside the ball with its top edge parallel to the target line.

Keep the complete board visible during calibration; re-calibrate whenever LM1 is moved.

For durable use, mount the print on a rigid, matte backing.