PrismX 3D Printer Bill of Materials

Quantity	Part	Remarks
	printed and/or molded plastic parts for PrismX 3D Printer	see Terawatt's PrismX github repo
	aluminum tie extrusion 20x20x400	
100	T-nuts M4 for slotted aluminum extrusions	
	ATX Power Supply with ATXPSUDevBoard adapter board	You will need an ATX power supply. It should have short-circuit and over-current protections. It needs to supply 30A of power on two (2) 12v rails. Almost all modern ATX supplies meet this criteria. Wattage isn't as important but usually a 300-350 watt or higher PSU will supply roughly 30A of 12v power. The ATXPSUDevBoard is optional but strongly recommended. Without it you'll need to hack your PSU to power the printer. With it you can use any ATX PSU; swap in a different PSU anytime; and access 3.3 v, 5v, and -12v lines for additional gadgets.
	Kysan Stepper Motor, NEMA 17	v, ev, and 12v interior additional gaugete.
	2 mm (GT2) Pitch, 497 Teeth, 6mm wide Single Sided Neoprene Belt with Fiberglass Cords	z-axis
	2 mm (GT2) Pitch, 590 Teeth, 6mm wide Single Sided Neoprene Belt with Fiberglass Cords	x and y axes
_	2 mm (GT2) Pitch,36 Teeth, 5mm Bore, Brass Insert, Polycarbonate Timing Pulley for 6mm Wide	in and y axes
2	Belt	x and z axes
	2 mm (GT2) Pitch,36 Teeth, 8mm Bore, Brass Insert, Polycarbonate Timing Pulley for 6mm Wide	
2	Belt	z-axis
4	2 mm (GT2) Pitch,48 Teeth, 5mm Bore, Brass Insert, Polycarbonate Timing Pulley for 6mm Wide	
	Belt Degree MK2 Heathed w// EDe resister and the resister	y-axis
	Reprap MK2 Heatbed w/LEDs, resistor, and thermistor	and representativities DOM
	00str00der Belt-Driven Extruder MK-VB Hotend	see reprap wiki for BOM
		or any J-head compatible hotend
12	LM8UU 8mm Linear Ball Bearing	or acrylic, or use our template on github to make your
1	Universal Y-Axis Plate Aluminum 0.1-inch thick	own
	Arduino MEGA 2560	other electronics like replicape will work
	RAMPS 1.4	other electronics like replicape will work
	A4988 Stepper Controller for RAMPS 1.4	other electronics like replicate will work
	8.03mm Bore, 15.9mm Panel hole dia, Self Lubricating Acetal Bearing.	z-axis bottom and top
	608-2RS Black Skateboard/Inline Skate/Rollerblade/Hockey Bearing Bronze Cage Ball Bearings	2 axio bottom and top
	8mm Shaft 406mm Straight Rail Linear Motion	
	8mm Shaft 495mm Straight Rail Linear Motion	
	Offilit Golding Chaight Nam Elifear Wolfon	original PrismX X-ends are designed for Terawatt
2	lead screw straight 330mm	leadscrew nut
		original PrismX x-ends are designed for Terawatt
	lead screw nut flanged	leadscrew nut
	Black Heat Shrink Tubing (4.5mm) 1m	cable mgmt
	Black Heat Shrink Tubing (6mm) 1m	cable mgmt
	Thrust Bearing 8x19x7 Miniature Thrust Bearings	z-axis
1	Fiberglass Sleeving, 3/8 In 1200 F Fiberglass, 1 Ft	extruder wiring

PrismX 3D Printer Bill of Materials

1 Fiberglass Sleeving, 1/4 In 1200 F Fiberglass, 1 Ft	extruder wiring
2 80mm Fan	(optional, almost) 1 for RAMPS, 1 for y-axis motor
1 40mm Fan	(optional) for print cooling
1 Reprap Wiring Kit	
16 Hi-temperature wire for RepRap heatbed and extruder heating elements - 1 FT. LENGTH	8 wires, 750mm each, 4x 18AWG for heaters, 4x 22-28AWG for thermistors