




## **Package Outline**








## Foot Print



## Marking Layout (Example)



## Standard Packing

Real p100 mm = 0.000 Pieces/Real Real p100 mm = 10.000 Pieces/Real

