

Figure 1: The most basic phasor diagram




Figure 2: The works




Figure 3: Phasor diagram of me testing




Figure 4: For large phasors, until an auto-scale is implemented, you can use scaleFactor, step, gridstep, and length to show large phasors on a more reasonable background