

## **FLIGHT CHECKLIST:**

Check battery voltage (12.0-12.6v) and insert
Make sure LIDAR and PX4FLOW are not covered
Make sure that ESCs are plugged in to the right pins
Make sure prop guards are secure
Make sure that the props are on in the correct direction (leading edge in)
Make sure that the props are not upside down
Make sure props are clear of any wire or structure
Make sure Kill Switch is in off position
Power on controllers
Make sure TELEM2 is unplugged
Plug in power loop
Turn Kill Switch to on position
Make sure ground station has good telemetry
Verify critical sensors are giving good data
Plug in TELEM2
SSH start/verify autonomous scripts are running
Make sure everyone is clear of drone
Verify mode switch in Stabilize
Hold safety button
Mode switch to Autonomous
Sit back, relax, and enjoy the ride