APPENDIX F.
RELATIVE IMPORTANCE OF THE PRINCIPAL COMPONENTS (PC)

	PC1	PC2	PC3	PC4	PC5	PC6	PC7	PC8
Standard deviation	3.07	2.34	2.27	2.14	1.77	1.33	0.69	0.00
Proportion of Variance	0.31	0.18	0.17	0.15	0.10	0.06	0.02	0.00
Cumulative Proportion	0.31	0.50	0.67	0.82	0.93	0.98	1.00	1.00