





```
1  PROGRAM PLC_PRG
2  VAR
3      // Entradas e Controle
4      firstScan      : BOOL ;
5      aux1 : BOOL ;
6      Remover_Plastico      : BOOL := TRUE ;
7      Remover_Metal      : BOOL := TRUE ;
8      xStart_Button      : BOOL ;
9      S_Capacitivo      : BOOL ;
10     S_Indutivo      : BOOL ;
11     xReset_Button      : BOOL ;
12     xStop_Button      : BOOL ;
13
14     // Lugares da Rede de Petri (BOOL para Metodologia de Kaid)
15     M_P0_Home      : BOOL ;
16     M_P1_Alimentacao      : BOOL ;
17     M_P2_Metal      : BOOL ;
18     M_P2_Plastico      : BOOL ;
19     M_P3_Desvia_Plastico : BOOL ;
20
21     // Sinais de Transição e Flags
22     S_T3_Plastico_Out : BOOL ;
23     S_T4_Metal_Out  : BOOL ;
24
25
26     // Atuadores
27     Emitter      : BOOL ;
28     Pusher      : BOOL ;
29     Conveyor_Motor : INT ; // Mantido como INT conforme sua solicitação
30
31     // Temporizadores e Triggers
32     T2_Wait_Pos      : TIME := T#2.5S ;
33     tonPos      : TON ;
```

```
34      trigReset      : R_TRIG ;
35
36      // Memórias das transições
37      M_T0_Start : BOOL ;
38      M_T1_Metal : BOOL ;
39      M_T1_Plastico : BOOL ;
40      M_T2_Wait_Pos : BOOL ;
41      M_T3_Pla_Out : BOOL ;
42      M_T4_Metal_Out : BOOL ;
43
44      END_VAR
45
```









20

aux1
()