
DC-12V INPUT
F1 2A
Q11
R85
D37
U12
R19
P2
P1
V2
V1
BUTTONS
GND
R18
R17
R16
J19
3V3 OUT
GND
+3V3
SDA
SCL
I2C_5
C68
C69
U13
R84
R82
R83
HOST 3V3 IN
SCL
SDA
+3V3
GND
QWIIC MASTER
3V3 OUT
SCL
SDA
+3V3
GND
QWIIC SENSOR
QWIIC SENSOR
GND
+3V3
SDA
SCL
3V3 OUT
QWIIC SENSOR
GND
+3V3
SDA
SCL
3V3 OUT
RheoBoard v1.05