Drag and Drop the server, 2 PC's, Laptop and Smartphone from End device



Drag and Drop home router from network devices



Use copper crossover wire for connection

Representation



Firstly off the green light then drag the HDMI part from laptop and add PT-LAPTOP-NM-1W to the empty part and later On the power button(green light).



IP config of Server



IP config of PC0, PC1, Smartphone and Laptop respectively









Ping command to check connectivity