## MODEL 463 as of model year 2013 /facelift 2012

- 1 Inside rearview mirror
- 2 Cover



P68.40-2203-06

XX	Remove/install		
1	Detach ground line from battery		AR54.10-P-0003GW
(1)	Notes on battery		AH54.10-P-0001-01A
2	Disconnect connector on electrical line from overhead control panel control unit (N70)		AR82.20-P-1000GW
3	Disconnect electrical connector from hands- free system microphone (A67b1)	i The separating point is located above the overhead control panel control unit (N70).	
4	Unclip cover (2)		
5	Remove rearview mirror (1)	i Unclip inside rearview mirror (1) from bracket downward at an angle.	
6	Install in the reverse order		
7	Read out and erase the fault memory using Star Diagnosis		AD00.00-P-2000-04A