

Data Erasure Report



Erasure Results

Disk: 1 (1-1)	Vendor: Micron Size: 512GB HPA: Doesn't exist Health Status: good	Model: 1100 SATA 512GB Bus: SATA/SSD DCO: Doesn't exist	Serial: 18261D509DF1 Sectors: 1000215216 Remapped Sector(s): 1
Remapped Sector(S) After Erasure:	1		
Start/End Time:	2023-04-01 08:17:11 (+0000) / 2023-04-01 08:30:12 (+0000)		
Duration:	00:13:01		
Method:	NIST 800-88 Clear		
Erasure Rounds:	2 (1 overwriting, 1 firmware based erasure)		
Status:	Erased		
Information:	Remapped sectors area was not erased by the user. Device is SSD, see manual for more information.		

Hardware Details

Manufacturer:	Dell Inc.
Chassis Type:	Notebook
Model:	Latitude 7490
Serial:	1PCZRQ2
UUID:	4c4c4544-0050-4310-805a-b1c04f525132
System SKU Number:	081C
Processor:	GenuineIntel, Intel(R) Core(TM) i5-8350U CPU @ 1.70GHz, Cores: 4, Stepping: 10, Nominal speed: 1700MHz, Max speed: N/A, External Clock: 100 MHz
Memory Bank:	80AD000080AD, 8192MB, 2400MHz, DDR4, SODIMM, Serial: 823278D0
Memory Bank:	Empty slot
Total Memory:	8192MB, Occupied memory banks: 1/2
Graphics Card:	Intel Corporation UHD Graphics 620, 32MB System memory reserved by EFI/BIOS
Current Resolution:	1920x1080
Sound Card:	Intel Corporation Sunrise Point-LP HD Audio
Storage Controller: 1	Intel Corporation 82801 Mobile SATA Controller [RAID mode]
Disk: 1 (1-1)	Micron, 1100 SATA 512GB, Firmware: M0DL022, Serial: 18261D509DF1, 512GB / 1000215216 sector(s), SATA/SSD, Sector Size: 512, Average Write Speed: 112MB/s, Average Read Speed: 369MB/s, Accessible Region: 512GB / 1000215216 sector(s), DCO: Doesn't exist, HPA: Doesn't exist, Remapped Sector(s): 1, Health Status: good, Self-test:
Wi-Fi Adapter: 1	Wireless, Intel Corporation Wireless 8265 / 8275 / Dual Band Wireless-AC 8265, 20:16:b9:5f:46:d2
Network Adapter: 1	Ethernet, Intel Corporation Ethernet Connection (4) I219-LM, e4:b9:7a:13:b8:ed
USB Device:	Intel Corp., Bluetooth wireless interface 2.00
USB Device:	Realtek Semiconductor Corp., Unknown model (0x58ca), CN0K0KM8LOG0087S0HELA00, Integrated_Webcam_HD 2.10
USB Device:	SanDisk Corp., Cruzer Blade, SanDisk, Cruzer Blade 2.00
Motherboard:	Dell Inc., 0KP0FT
BIOS:	Dell Inc., Version: 1.19.0, Date: 02/23/2021, Features: PCI, PNP, ACPI, CD Boot, EDD, Legacy USB
Ports:	USB Ports: 3, HDMI: 1
Battery:	Vendor: LGC-LGC7.780, Model: DELL MYJ9686, Serial: 31432, Type: Li-ion, Capacity: 5726 / 7894 mAh, Voltage: 7728 mV
TPM:	Nuvoton Technology, Version: 2.0, Firmware: 7.2

Report Details

Report UUID:	7fec1be9-c9f4-4489-bc4f-48e62f723462
Report Date:	2023-04-01 08:30:59 (+0000)
Software Version:	Blanco Drive Eraser 7.5.1
Digital Signature:	

CBHZe+pM7XmG5Mubt++1yHquUMyQWACnfeHvgBZIoG9tYXqHixwjee3oGwMWVVKRjkU9Smf+Le6IL6cmprnBv/VL2/TUk5WKzF/C9XdDPGprlAt4qrOimijYzvrPDvKGsO2+L412N1SZvjxGuMjRXtEeMSXZz+Rgy+rn48B1qya+K3+/oVotVewemKpdlLjOezaCcWWZZznWKK0an86lb06sBE4Qg3B4ATfpXwtXSAWlzn0GkDzQXPLeE1YTgbkfgaXSAFBcbeFyrTkdnPt4IHkS6Z1bbBK4m1wUvc9cXq2WEAu5Hnz1vHfZNACrPfiUN4iwBO08xtJlQPtLA8w==

OPERATOR

SUPERVISOR