

<mohankumarvutukuri@hsbc.co.in>; Biswarup GHOSH <biswarupghosh@hsbc.co.in>
Subject: EXTERNAL: RE: RE: Request Outward from CtrlS DC3

Dear Sir,

Greetings !

Payment is under process against attached invoice, once is complete will share the UTR details here.

We will check the availability of FE and update you accordingly.

Thanks & Regards,
Neeraj Kumar
9910089204

From: Muhesh KURUP <muhesh.kurup@hsbc.co.in>
Sent: Monday, June 16, 2025 2:26 PM
To: Soumendranath DAS <soumendranath.das@hsbc.co.in>; Sweta <sweta@Dwmpl.com>; Arti TAWDE <artitawde@hsbc.co.in>; Neeraj Kumar <neeraj.kumar@Dwmpl.com>; Mona Yadav <mona.yadav@Dwmpl.com>
Cc: Rahul Mondal <rahul.mondal@Dwmpl.com>; #IndiaITID_ES_Server_Support <indiaitid.es.server.support@hsbc.co.in>; Sanidhya Kashyap <sanidhya.kashyap@Dwmpl.com>; Ashwani <ashwani@Dwmpl.com>; Arvinder Singh <arvinder.singh@Dwmpl.com>; Vilas Sudhakar DESHMUKH <vilas.sudhakar.deshmukh@hsbc.co.in>; Rishi Pandey <rishi.pandey@Dwmpl.com>; Anil SHIRASKAR <anil.shiraskar@noexternalmail.hsbc.com>; Syed Manauar AHSAN <syedmanauarahsan@hsbc.co.in>; Neeraj Kumar <neeraj.kumar@Dwmpl.com>; Fayaz GHOUSE <fayazghouse@hsbc.co.in>; Arun Kumar P R <arunkumar.pr@us.hsbc.com>; Mohan Kumar VUTUKURI <mohankumarvutukuri@hsbc.co.in>; Biswarup GHOSH <biswarupghosh@hsbc.co.in>
Subject: RE: EXTERNAL: RE: Request Outward from CtrlS DC3

Hello Sweta/Neeraj,

Except for the enclosed PO, we have a few additional items that need to be scrapped. Could you please arrange for someone to inspect the materials listed below and obtain quotes?

OLD PART details:-

SR.NO	Part Discription	Serial Number	QTY	Activity date/Inward date	Reamrk
1	PowerMax	FXTLA214500197	2	02-11-2024	Pmax upgraded/old part
2		FXTLA212700053			

SR.NO	Activity date	Part Discription	Part Serial Number
1	17-05-2025	DS-X97-SF1-K9 V03 (Supervisor Card)	JAE20240CWP
2		DS-X97-SF1-K9 V03 (Supervisor Card)	JAE202406L0
3		DS-X9710-FAB3 V01 (xbar fabric module)	JAE202104L9
4		DS-X9710-FAB3 V01 (xbar fabric module)	JAE202202RY
5		DS-X9710-FAB3 V01 (xbar fabric module)	JAE202202V3

SR.NO	Activity date	Part Discription	Part Serial Number
1	18-05-2025	DS-X97-SF1-K9 V03 (Supervisor Card)	JAE2024087W
2		DS-X97-SF1-K9 V03 (Supervisor Card)	JAE20240BN3
3		DS-X9710-FAB3 V01 (xbar fabric module)	JAE202202RW
4		DS-X9710-FAB3 V01 (xbar fabric module)	JAE202202PS
5		DS-X9710-FAB3 V01 (xbar fabric module)	JAE202202RR

SR.NO	Activity date	Part Discription	Part Serial Number
1	24-05-2025	DS-X9448-768K9 V02 (48 Port FC Card)	JAE203601SP
2		DS-X9448-768K9 V02 (48 Port FC Card)	JAE201701RT

SL No	Device Details	Device Details	Serial NO
17	DD DS60 SHELF UPG , HDD DISK PK 15X8TB SAS FL DS60 UPG (Data domain capicity upgrade material)	1	S/N: 5MFG414
18	DD DS60 SHELF UPG , HDD DISK PK 15X8TB SAS FL DS60 UPG (Data domain capicity upgrade material)	1	S/N:J6JG414
19	Faulty NetApp Controller	1	faulty S/N: 9522320018
20	DELL EMC Power protect DD9400	1	SN # CKM0122070559 Service Tag: 1F7QPM3

Regards,

Muhesh Kurup