IA9100 DRAFT 8.1.4 b · OBSOLESCENCE · WAS GUIDANCE

Which part you buy is closest to end of life?

In the draft, counterfeit prevention moves from guidance to requirement, obsolescence monitoring included.

1. Watch-list the parts you can't easily substitute
2. Record each source, and whether it's authorized
3. Date the last status check, and name who checks next
4. Put the review on a calendar
5. When a notice comes, stay with approved sources

Swipe: one action per page, with the record that proves it.

ACTION 1 OF 5 · DRAFT 8.1.4 b

WAS GUIDANCE, NOW A REQUIREMENT

Watch-list the parts you can't easily substitute

Sole-source parts, long lead-time materials, electronic parts, anything the drawing names by manufacturer.

THE RECORD THAT PROVES IT

- ☐ The obsolescence watch list

> **Watch for:** Hearing from the distributor that a part is on allocation. That's where counterfeiters like you to be.

ACTION 2 OF 5 · DRAFT 8.1.4 c

WAS GUIDANCE, NOW A REQUIREMENT

Record each source, and whether it's authorized

Original manufacturer, authorized distributor, or a source you approved on purpose.

THE RECORD THAT PROVES IT

- ☐ The approved supplier list, showing each source's authorization

> **Sample plant:** Case CF-MER-002: a certificate from an unlisted distributor, under investigation.

ACTION 3 OF 5 · DRAFT 8.1.4 b

WAS GUIDANCE, NOW A REQUIREMENT

Date the last status check, and name who checks next

For each part on the list: its status from the manufacturer, when it was checked, and by whom.

THE RECORD THAT PROVES IT

- ☐ Watch-list columns: status, last checked, checked by, next check

> **Small shop:** This needn't be software. A list with dates and a name is the evidence.

ACTION 4 OF 5 · DRAFT 8.1.4 b

WAS GUIDANCE, NOW A REQUIREMENT

Put the review on a calendar

Quarterly is a fair start. Each review: check the status, update the dates, act on anything near end of life.

THE RECORD THAT PROVES IT

- ☐ The calendar entry, and each dated review

Watch for: A list built once and never reviewed. The dates will show it.

ACTION 5 OF 5 · DRAFT 8.1.4 c

WAS GUIDANCE, NOW A REQUIREMENT

When a notice comes, stay with approved sources

Plan a last-time buy or an approved alternate while there is time, so a short deadline doesn't push you to an unknown broker.

THE RECORD THAT PROVES IT

- ☐ The purchase order to an approved source
- ☐ The receiving record with its source checks

> **Sample plant:** Case CF-MER-001: broker parts with head markings unlike the manufacturer's, in quarantine.

THE RECORD · A PLACE TO START

An obsolescence watch list on one page

OBSOLESCENCE WATCH LIST			REVIEW QUARTERLY	
PART OR MATERIAL	SOURCE	AUTHORIZED?	STATUS · CHECKED	NEXT · WHO

In the draft: counterfeit prevention (8.1.4) moves from guidance to requirement, including a parts obsolescence monitoring program.

BEFORE YOUR TRANSITION AUDIT

See where your records stand on each IA9100 change

1. For each new or changed requirement: shown, partly shown, a gap, or can't be judged from what you sent
2. A ranked action plan to close the gaps before your transition audit
3. Built from the quality records you already keep, in our Excel templates, plus a short set of transition questions

> **IA9100 is not yet final.** The IA9100 Transition Gap Analysis is measured against the IA9100 changes the IAQG has published to date, and the final text may still change these topics. It is not certification or a registrar audit.

www.aegis-aeroassure.com/ia9100-gap-analysis