# CLO / SKCL (Cali, Colombia) (Elev. 3162')

- → Engine Failure procedures. For Rwy. 02, Consider climb to 6000'. Reference approach altitude at LOMIM Fix. For Rwy. 20, Consider climb to 8000'. Reference approach altitude at SIPOG Fix.
- → **Depressurization Routes** To/From this airport. See Diversion Guide. \*\*Consider West deviation toward ocean., see terrain ref. chart (10-1R).
- See <u>International Supplement</u> in the back of this document for RNP4 procedures required over some portions of the Caribbean Sea which may exceed 162 NM.
- FYI, Cali airport sits in a very wide, flat valley.
- Customs: No customs forms.
- COVID: See the last page of this guide for information on locating the latest COVID information and tips on completing the Colombian Check-Mig form.
- Arrival routes this section: MIA to CLO 1, 2

### MIA to CLO – 1

- → With calm winds, consider calling ahead to confirm active runway.
- → Landing North, Request TULUA 4E arrival and to descend via the arrival. ATC may refer to this as "ULQ4E" & Request ILS Y approach which connects nicely to the ILS.
- → Descend cruise MACH to 280 Kts. Cross ULQ @ 280/16000A.
- → Plan 240/13000'.
- → NIGRU @ 210 Kts.
- → PALOV @ 190 Kts.

-----

→ Option: "ULQ6D" TULUA 6D Arrival (landing North). ULQ25 - 230/13000A, CLO112 – 200/8000A, ILS Z.

| HAV r    | 120.25 / 123.7 | URSUS                 |
|----------|----------------|-----------------------|
| KIN r    | 125.4 / 128.1  | PUTUL                 |
| BAQ r    | 128.4          | KILER / OTAMO / SUDSA |
| BAQ      | 124.2 S        | -                     |
| BOG r    | 123.7          | -                     |
| CLO App. | 119.1          | -                     |

### MIA to CLO – 2

See arrival notes above.

| HAV r    | 120.25 / 123.7 | URSUS         |
|----------|----------------|---------------|
| KIN r    | 125.4 / 128.1  | BEMOL / EMABU |
| BAQ r    | 128.4          | KILER / OTAMO |
| BOG r    | 123.7          | BUTAL         |
| CLO App. | 119.1          | -             |

## **DEPARTURE - E/O's Variable**

- → Engine Failure procedures. For Rwy. 02, Consider climb to 6000'. Reference approach altitude at LOMIM Fix. For Rwy. 20, Consider climb to 8000'. Reference approach altitude at SIPOG Fix.
- → Climb for terrain ~ 220/16000'. See terrain ref. chart (10-1R).
- Approaching US, logon to CPDLC.
- Departures routes this section: CLO to MIA 1, 2, 3

### CLO to MIA - 1

- → Expect SIGI 5C or TULUA 9B Dep. (ULQ 9B) LNAV.
- → Expect clearance to cross 10NM South of ULQ 12000A (FMC: ULQ/-10 @ 12000A).
- → May request direct KILER from Departure.

| 119.1          | Dep.   |
|----------------|--|
| 123.7          | -  |
| 124.2          | -  |
| 128.4          | -  |
| 125.4 / 128.1  | KILER  |
| 123.7 / 120.25 | BEMOL  |
| 126.32         | ENAMO  |
|                | 123.7<br>124.2<br>128.4<br>125.4 / 128.1<br>123.7 / 120.25 |

### CLO to MIA - 2

• See departure notes above.

| BOG r | 119.1          | Dep.          |
|-------|----------------|---------------|
| BOG   | 123.7          | -             |
| BAQ r | 124.2 S        | BUTAL         |
| BAQ   | 128.4          | -             |
| KIN r | 125.4 / 128.1  | KILER         |
| HAV r | 120.25 / 123.7 | PUTUL / EPSIM |
| MIA   | 126.32         | URSUS / ZEUSS |

### CLO to MIA - 3

• See departure notes above.

| CLO r | 119.3          | Dep.          |
|-------|----------------|---------------|
| BOG r | 125.1          | -             |
| PTY r | 123.3 ?        | BUSMO         |
| u     | 133.3 N        | -             |
| KIN r | 125.4 / 128.35 | ARNAL         |
| HAV r | 124.55 / 133.7 | ATUVI         |
| "     | 133.35         | -             |
| MIA   | 132.2 / 124.7  | IKBIX / FUNDI |

■ ■ ■ <u>A/P INDEX</u> / <u>HOME</u>