HOW GREASE?

NOTE #1:

Relubrication: Most bearings can be relubricated with a high quality NLGI#2, lithium soap grease with petroleum oil. Always wipe the fitting and grease gun nozzle clean. For safety, stop rotating equipment. Add grease slowly until a small bead of grease is present at the seals. Start equipment slowly, if more purging of the grease is necessary, stop equipment and repeat above.

NOTE #2:

Clean surface well. Before spraying new grease, make sure the surface is clean from all contamination. Spray uniformly on all apparent surface. Use aerosol grease with specifications of reducing friction and wear, and offering outstanding rust protection. Coats with a non brittle film which resists heavy pressure, extreme temperatures and water.