







C191, C192, C193 omitted on reloaded board - parity generator bypass caps






Macintosh IIfx logicboard

power bypass & decoupling




Page 4 of 13




Macintosh IIfx logicboard

SCSI controller


Page 5 of 13






Macintosh IIfx logicboard

OSS & VIA






Macintosh IIfx logicboard

68030 & 68882  
slow/fast buffers

Page 7 of 13








Macintosh IIfx logicboard

PALs  
PDS

Page 8 of 13









Macintosh IIfx logicboard

RAM








Macintosh IIIfx logicboard

BIU30/BIU2  
Nubus clock gen.  
Nubus termination

Page 11 of 13







Macintosh IIIfx logicboard

Audio

