








C191, C192, C193 omitted on reloaded board - parity generator bypass caps






Macintosh IIfx logicboard

power bypass & decoupling





Page 4 of 13



Macintosh IIfx logicboard

SCSI controller






Macintosh IIfx logicboard




OSS & VIA


Page 6 of 13




Macintosh IIfx logicboard

68030 & 68882
slow/fast buffers












Macintosh IIfx logicboard

BIU30/BIU2
Nubus clock gen.
PDS

Page 11 of 13







Macintosh IIIfx logicboard

Audio

