## DC BRUSHED MOTOR:

Optimal working voltage: 5V~8VDC. Batch Number: Double Axis 1:48 Load Current:  $\leq 150mA$  (200mA MAX)

