											1.0
B1	1	0.25	-0.34	0.042	0.014	0.4	0.52	-0.03	0.6		
B2 -	0.25	1	-0.14	0.032	-0.077	0.69	0.75	-0.12	0.69		- 0.8
B3 '	-0.34	-0.14	1	-0.068	-0.031	0.14	0.15	-0.099	0.12		- 0.6
LT01	0.042	0.032	-0.068	1	0.038	-0.0013	0.029	0.97	0.16		
FT01	0.014	-0.077	-0.031	0.038	1	0.018	-0.015	0.046	-0.031		- 0.4
FT02	0.4	0.69	0.14	-0.0013	0.018	1	0.87	-0.18	0.68		- 0.2
FT03	0.52	0.75	0.15	0.029	-0.015	0.87	1	-0.15	0.84		- 0.0
PT01	-0.03	-0.12	-0.099	0.97	0.046	-0.18	-0.15	1	0.02		
PT02	0.6	0.69	0.12	0.16	-0.031	0.68	0.84	0.02	1		0.2
	В1	B2	B3	LT'01	FT01	FT02	FT03	PT01	PT02		