										1.0	
B1	1	0.37	-0.062	-0.24	0.085	0.42	0.8	-0.32	0.88	1.0	
B2 -	0.37	1	-0.51	-0.28	-0.064	0.27	0.52	-0.32	0.54	- 0.8	
B3 -	-0.062	-0.51	1	-0.15	0.089	0.13	0.16	-0.18	0.12	- 0.6	
LT01	-0.24	-0.28	-0.15	1	0.047	-0.27	-0.34	0.96	-0.32	- 0.4	
FT01	0.085	-0.064	0.089	0.047	1	0.29	0.18	0.01	0.06	- 0.2	
FT02	0.42	0.27	0.13	-0.27	0.29	1	0.64	-0.34	0.47	- 0.0	
FT03	0.8	0.52	0.16	-0.34	0.18	0.64	1	-0.45	0.91	0.0	
PT01	-0.32	-0.32	-0.18	0.96	0.01	-0.34	-0.45	1	-0.41	0.2	?
PT02	0.88	0.54	0.12	-0.32	0.06	0.47	0.91	-0.41	1	0.4	Į
	B1	B2	B3	LTO1	FT01	FT02	FT03	PT01	PT02		