										,	1 0
B1	1	0.2	0.12	-0.41	0.75	0.6	0.86	-0.51	0.91		1.0
B2 -	0.2	1	-0.44	-0.23	0.4	0.34	0.48	-0.29	0.45	- (0.8
B3 -	0.12	-0.44	1	-0.2	0.24	0.25	0.27	-0.25	0.23	- (0.6
LT01	-0.41	-0.23	-0.2	1	-0.48	-0.51	-0.49	0.98	-0.44	- (0.4
FT01	0.75	0.4	0.24	-0.48	1	0.86	0.86	-0.58	0.86	- (0.2
FT02	0.6	0.34	0.25	-0.51	0.86	1	0.72	-0.59	0.69	- (0.0
FT03	0.86	0.48	0.27	-0.49	0.86	0.72	1	-0.62	0.97	- <u>-</u>	-0.2
PT01	-0.51	-0.29	-0.25	0.98	-0.58	-0.59	-0.62	1	-0.57		-0.4
PT02	0.91	0.45	0.23	-0.44	0.86	0.69	0.97	-0.57	1		-0.6
	B1	B2	B3	LTO1	FT01	FT02	FT03	PT01	PT02		0.0