```
Sensor
- max_i2c_buffer size
+ Sensor()
+ ~Sensor()
+ name()
+ sid()
+ rsid()
+ setUp()
+ getStringForDisplay()
+ getExtendedStringForDisplay()
+ readSensor()
+ saveConfig()
+ getJson()
+ setJson()
+ readFeature()
+ createSensorObject()
+ createFeaturesArray()
+ createXSettingsArray()
+ createlSettingsArray()
+ fillBasicInfo()
+ generateFeatures()
+ generateXSettings()
+ generatelSettings()
+ generateTemplatedSensorObject()
+ generateTemplatedSensorObject()
and 19 more...

    read()

features_JsonSetter()
xSettings_JsonSetter()
iSettings_JsonSetter()
              INA3221
        rsid

    activeFeaturesVec

    xSettings

    wire

       _shunt_resistor

    isonFilePath

    inaFeaturesString

      + INA3221()
      + getBusVoltage_V()
      + getShuntVoltage_mV()
      + getCurrent mA()
      + getManufID()
      + wireWriteRegister()
      + wireReadRegister()
      + INA3221SetConfig()
      + getBusVoltage_raw()
      + getShuntVoltage_raw()
      and 11 more...
```