

UNIVERSITY OF GHANA

All Rights Reserved

FACULTY OF ENGINEERING SCIENCES BSc. (ENG) SECOND SEMESTER EXAMINATIONS: 2011/2012

MTEN 202 Kinetics and Surface Phenomena (2 Credits)

Answer All Questions

Time Allowed: 2hours

Section A

- 1. Compare the activation energies of interstitial and vacancy diffusion as well as the activation energy of low and high melting point materials
- 2. What is self diffusion and how will you experimentally measure self diffusion in a normal material like Ni.
- 3. Both the atomic and statistical aspect of Diffusion may be summed up by diffusion equations called Fick's Laws. State these laws and interpret them and then give the conditions under which these laws apply respectively.
- 4. Using a sketch diagram, state Young's equation of a wetting surface
- 5. Rewrite the expression for the total free energy change for nucleation for the case of a cube nucleus of edge 'a' (instead of 'r' for a sphere). Is ΔG* greater for a cube or a sphere.
- 6. What is the difference between homogenous and heterogeneous nucleation and why is the activation energy for nucleation lower in heterogeneous nucleation.
- 7. Sketch the concentration profile for nonsteady state diffusion taken at three different times.
- 8. Define a surface and name three different surfaces as applied in surface science.
- 9. Differentiate between cohesive and adhesive force
- 10. Using a sketch diagram differentiate between a wetting and dewetting surface.



Examiner: Dr. Johnson Efavi

Page 1



- 1. (a) For the solidification of pure gold, calculate the critical radius and the activation free energy if nucleation is homogeneous. Values for the latent heat of fusion and surface free energy are J/m3 and 0.132 J/m2, respectively. Use the supercooling value (ΔT) of 230°C.
 - (b) For some transformation having kinetics that obey the Avrami equation, the parameter n is known to have a value of 1.5. If, after 125 s, the reaction is 25% complete, how long (total time) will it take the transformation to go to 90% completion?
 - (c) It is known that the kinetics of recrystallization for some alloy obey the Avrami equation, and that the value of n in the exponential is 5.0. If, at some temperature, the fraction recrystallized is 0.30 after 100 min, determine the rate of recrystallization at this temperature.
- 2. (a) A sheet of steel 2.5mm thick has nitrogen atmospheres on both sides at 900°C and is permitted to achieve a steady-state diffusion condition. The diffusion coefficient for nitrogen in steel at this temperature is 1.2*10⁻¹⁰ m²/s, and the diffusion flux is found to be 1.0*10⁻⁷ kg/m²-s. Also, it is known that the concentration of nitrogen in the steel at the high-pressure surface is 2 kg/m³. How far into the sheet from this high pressure side will the concentration be 0.5kg/m³? Assume a linear concentration profile.
 - (b) Determine the carburizing time necessary to achieve a carbon concentration of 0.30 wt% at a position 4 mm into an iron-carbon alloy that initially contains 0.10 wt% C. The surface concentration is to be maintained at 0.90 wt%C, and the treatment is to be conducted at 1100° C. Use the diffusion data for γ -Fe in Figure 1.

Diffusing Species	Host Metal					
			Activation Energy Qa		Calculated Values	
		$D_0(m^2/s)$	kJ/mol	eV/atom	T(°C)	$D(m^2/s)$
Fe	α-Fe (BCC)	2.8×10^{-4}	251	2.60	500 900	3.0×10^{-21} 1.8×10^{-15}
Fe	γ-Fe (FCC)	5.0×10^{-5}	284	2.94	900 1100	1.1×10^{-17} 7.8×10^{-16}
С	α-Fe	6.2×10^{-7}	80	0.83	500 900	$\begin{array}{c} 2.4 \times 10^{-12} \\ 1.7 \times 10^{-10} \end{array}$
С	γ-Fe	2.3×10^{-5}	148	1.53	900 1100	5.9×10^{-12} 5.3×10^{-11}
Cu	Cu	7.8×10^{-5}	211	2.19	500	4.2×10^{-19}
Zn	Cu	2.4×10^{-5}	189	1.96	500	4.0×10^{-18}
Al	Al	2.3×10^{-4}	144	1.49	500	4.2×10^{-14}
Cu	Al	6.5×10^{-5}	136	1.41	500	4.1×10^{-14}
Mg	Al	1.2×10^{-4}	131	1.35	500	1.9×10^{-13}
Cu	<u>Ni</u>	2.7×10^{-5}	256	2.65	500	1.3×10^{-22}

Figure 1: Some Diffusing Tabulation Data for some Species