

Greetech Razer Green		
Switch Type: Clicky		Greetech
17	/35	Push Feel
13	/25	Wobble
3	/10	Sound
6	/20	Context
4	/10	Other
43	/100	Total

*Notes*Push Feel

Even amongst other Greetech made Razer switches, the Greens are unique mushy and have an almost grainy like feeling clickjacket mechanism that makes for a dull and flat click bump. About the only saving grace for these otherwise incredibly scratchy switches are a pair of house collisions that are at least somewhat thick and doesn't make the switch feel so cheap.

Wobble

Hardly out of commonplace for switches from around 2015 when these were manufactured, these Razer Greens have a large amount of N/S and E/W stem wobble that is nearly circularly with an E/W top housing wobble that may or may not be fixable via the usage of films.

Sound

These truly are an absolute nightmare in the clicky-switch sound department. While already having a muted, flat, lifeless feeling click mechanism, the similar sound that accompanies this is nearly drowned out by the loud spring ping, mechanical crunching, and other sound oddities that don't pop up consistently on each and every stroke.

Context

While these were only briefly featured in a narrow range of Razer branded keyboards from around 2015, these take a hit when comparing them next to Greens made by other manufacturers throughout the years. Not counting the improvements in technology over this time, these don't even stand up as viable options relative to other clicky switches of the time. There's not all that much more you could do to really spit in your customers' faces to be honest.

Other

These are not only the worst of the Greetech made Razer options from switch history, but are bar none some of the worst MX-style clicky switches I've ever had the (mis)fortune of trying. I'm quite thankful that these will forever remain as a small, and albeit unremarkable footnote.