

DETERMINE THE LOCATION AND ORIENTATION OF THE SHELF (SHELF MAY BE MOUNTED WITH THE LIP UP OR THE LIP DOWN.)

DRILL 11/32" HOLES IN THE TOOL BOX ENDS. HOLE SIZE IS CRITICAL FOR BOLT SEATING. MOUNT ANGLES TO THE TOOL BOX END USING CARRIAGE BOLTS.

INSERT SHELF AND MOUNT TO ANGLES USING CARRIAGE BOLTS.

TORQUE ALL NUTS TO 19 FT. LBS.

PERIODICALLY CHECK AND MAINTAIN TORQUE ON ALL NUTS.

26400

	ш,	2	87-9900-284	ANGLE, 24"D TOOL BOX SUPPORT
	Ш	1	REF	SHELF, TOOL BOX
		12	11-2010	NUT, 5/16"-24 NYLON LOCK NUT
	0	: 12	11-7035	WASHER, 5/16" SAE WASHER
	8	12	11-8241	5/16" X 1" CARRIAGE BOLT
	<b>*</b>	-	REF	24"D TOOL BOX
	LITEM	M OTY	PART NUMBER	DESCRIPTION
Z LTR DATE	DESCRIPTION	ΒY	SCALE NONE	
Q			DWN BY: TPK	MERRITI EQUPMENT CO.
S			# 33.6	9339 - HWY 85 HENDERSON, COLORADO 60640 1 (600) 525 0107
1/			, P. C. II	THE N LOW CHELD
SE/			WEIGHT	IIILE MOUNTING INSTRUCTIONS
}			DATE 2/25/08	DATE 2/25/08 DWG LSRSD0101