

Lockout/Tagout Safety Procedure

This procedure establishes the minimum requirements for the lockout of energy-isolating devices whenever maintenance or servicing is performed on machinery or equipment.

Section 2: Responsibilities

Authorized employees shall verify isolation of energy sources before beginning work. Affected employees shall be notified before lockout devices are applied or removed.