Typhoon OpenDSS 0.5.1

Release Notes

Compatible with Typhoon HIL Control Center 2024.3

- Improvements/bugfixes:
 - Generator stability improvements and fixes to the incorrect power and voltage units in the mask description of the Generator Controller.
 - Load mask bugfixes in transition between load types.
 - o Fixed Vsource container.
 - o Updated handling of time series inputs on the SimDSS component.
 - o Added property to change meter's snubbers on the Monitor component.
- Added Examples:
 - o EPC Power CHIL Interface using container component.