
START
Wait for command
Read inputted Command
CTRL + c
"On"
"Off"
"Exit / Quit"
LED off
GPIO = False
GPIO.cleanup
End loop
LED ON
GPIO.output(18, True)
LED OFF
GPIO.output(18, False)
LED off
GPIO = False
GPIO.cleanup
Repeat = False
End loop
Stops program
Ends program
Wait for next command