## RASPBERRY PI ZERO POWER SENSOR HAT

## TABLE OF CONTENTS

SHEET	SHEET NAME
1	TITLE_TOC
2	BLOCK_DIAGRAM
3	LIPO_CHARGER_AND_RESET
4	POWER_ENTRY_BOOST_LDO
5	SENSORS
6	PI_MCU_CONNECT_AND_MOUNTING
7	ASSEMBLY_COMPONENTS
8	
9	
10	

TEAM: P17105

ENGINEER: CHRIS SCHWAB

TITLE\_TOC

TITLE: raspi\_zero\_power\_sensor\_hat

Document Number:

Date: not saved! Sheet: 1/7











