

SOUTHMERE SPARK

TEST SERVICES / ELECTRICAL JOB SLIP

Job reference

SS-TEST-MISSING-03

Customer

Florence Ash

Service property

41 Makebelieve Crescent
South Exampleton, ZZ3 4DD

WORK COMPLETED

Replaced damaged double socket in the upstairs study.
Tested socket operation and earth continuity after fitting.

Office copy - job summary only.
Please contact the office for billing details.