## CHICAGO COIN

# TV PING PONG

(MODEL 424)

PARTS CATALOG

CHICAGO DYNAMIC INDUSTRIES, INC.

1725 DIVERSEY BOULEVARD CHICAGO, ILLINOIS 60614 PHONE (312) 935-4600

#### INTRODUCTION

THIS PARTS CATALOG HAS BEEN COMPILED TO HELP THE SERVICEMAN IN SELECTING THE PARTS NECESSARY FOR PROPER MAINTENANCE OF CHICAGO COIN GAMES.


WHEN ORDERING PARTS ALWAYS SPECIFY NAME OF UNIT, PART NUMBERS AND A DESCRIPTION OF THE PART AS SHOWN IN THIS CATALOG.

#### WARRANTY

CHICAGO COIN WARRANTS THE SOLID STATE MODULE No. 424-2500
TO BE FREE FROM DEFECTS IN MATERIAL AND WORKMANSHIP ARISING
FROM NORMAL USAGE FOR 6 MONTHS FROM DATE OF ORIGINAL CONSUMER
PURCHASE. WARRANTY COVERS REPLACEMENT OR REPAIR OF THIS
MODULE THROUGH AN AUTHORIZED CHICAGO COIN DISTRIBUTOR. \* ONLY
UNDER THE CONDITION THAT IT HAS NOT BEEN TAMPERED WITH.
TRANSPORTATION CHARGES ARE THE OBLIGATION OF OWNER.

CHICAGO DYNAMIC INDUSTRIES
PARTS CATALOG

## ADJUSTMENT FOR FRONT T.V. CONTROLS (to be adjusted only if necessary)



1. OFF-ON VOLUME CONTROL

SWITCH MUST BE LEFT ON. SET VOLUME FOR LOCATION.

#### 2. BRIGHTNESS CONTROL

SET TO MAXIMUM (CLOCKWISE) AND BACK OFF (COUNTER CLOCKWISE) JUST WHEN BACKGROUND GOES BLACK.

#### 3. CONTRAST CONTROL


SET TO MAXIMUM (CLOCKWISE) AND BACK OFF CONTRAST CONTROL JUST TO THE POINT THAT THE RIGHT SIDE OF THE HORIZONTAL BARS IN THE SCORE LINES UP WITH THE VERTICAL BARS. (THE PICTURE ABOVE SHOWS TOO MUCH CONTRAST).

NOTE: CHANNEL CONTROLS ARE INOPERATIVE. THEIR POSITION HAS NO EFFECT.

CHICAGO DYNAMIC INDUSTRIES

PARTS CATALOG

PAGE 2



## ADJUSTMENT FOR T.V. REAR CONTROLS (to be adjusted only if necessary)


- 1. THE VERTICAL HOLD CONTROL COMPENSATES FOR CHANGES WHICH CAUSE THE PICTURE TO ROLL. TURN THE VERTICAL HOLD KNOB IN EITHER DIRECTION UNTIL THE PICTURE LOCKS FIRMLY IN POSITION.
- 2. THE HORIZONTAL HOLD CONTROL IS USED TO STEADY THE PICTURE WHEN A SERIES OF DIAGONAL BARS OR A SIDEWAYS MOTION IS PRESENT. TURN THE CONTROL IN EITHER DIRECTION UNTIL THE SIDEWAYS MOVEMENT OR BARS ARE ELIMINATED AND THE PICTURE IS STEADY ON THE SCREEN.



HORIZONTAL HOLD ADJUSTMENT NEEDED

CHICAGO DYNAMIC INDUSTRIES


PARTS CATALOG



CHICAGO DYNAMIC INDUSTRIES

PARTS CATALOG


PAGE 4




CHICAGO DYNAMIC INDUSTRIES

PARTS CATALOG


PAGE "5





### CHICAGO DYNAMIC INDUSTRIES


PARTS CATALOG




ITEM	PART NO.	DESCRIPTION
1		LIGHT BOARD ASSEMBLY (SEE PAGE B)
2	424-300	19" T.V. SET
3	424-504	T.V. SIDE RETAINER BRACKET
4	378-579-A	HOLDING BRACKET
5	424-301	COIN CHUTE & PLATE ASS'Y (SPECIFY COIN)
6	#302	ANTI-CHEAT SWITCH
7	424-503	GLASS LOCK BOLT (14" LG.)
	216-530	SAFETY LATCH
8	#5700	TOGGLE SWITCH
9	424-505	T.V. FRONT RETAINER BRACKET
10	#5701-D	PARALLEL POLARIZED CONVENIENCE OUTLET
1.1	424-2500	SOLID STATE MODULE (SEE PAGES 4 & 5)

CHICAGO DYNAMIC INDUSTRIES

PARTS CATALOG





CHICAGO DYNAMIC INDUSTRIES
PARTS CATALOG

PAGE 8

## T. V. PING PONG

( MODEL 424)

