This equipment has not been tested to show compliance with new FCC Rules (47 CFR Part 15) designed to limit interference to radio and television reception. Operation of this equipment in a residential area is likely to cause unacceptable interference to radio communication requiring the operator to take whatever steps are necessary to correct the interference.