Schematically, the connection of the steppers is unimportant, because the connection from our stepper driver to our steppers is a directional connector. that comes with the steppers

