






tips at 18 deg: place carefully







tips at 18 deg: place carefully



move robot: +x -> assembly spot: -y
board x [-7.58, 12.42] cm, y [-9.42, 19.28] cm
blue: on the board (dashed: support area, dots: contact corners)

10 cm (print at 100%, no "fit to page")