

4
move
5
move
tips at 18 deg: place carefully
2
move
0
move
tips at 18 deg: place carefully
3
hold
1
move
move robot: +x -> assembly spot: -y
board x [-2.00, 26.70] cm, y [-16.25, 3.75] cm
blue: on the board (dashed: support area, dots: contact corners)
10 cm (print at 100%, no "fit to page")