





tips at 18 deg: place carefully



move robot: +x -> assembly spot: -y
board x [-12.85, 7.15] cm, y [1.10, 29.80] cm
blue: on the board (dashed: support area, dots: contact corners)

10 cm (print at 100%, no "fit to page")