






tips at 14 deg: place carefully




tips at 17 deg: place carefully



tips at 17 deg: place carefully



tips at 17 deg: place carefully





tips at 17 deg: place carefully

move robot: +x -> assembly spot: -y
board x [-7.76, 12.24] cm, y [-3.33, 25.37] cm
blue: on the board (dashed: support area, dots: contact corners)

10 cm (print at 100%, no "fit to page")