











tips at 18 deg: place carefully

tips at 18 deg: place carefully





move robot: +x -> assembly spot: -y
board x [-13.40, 6.60] cm, y [-6.68, 22.02] cm
blue: on the board (dashed: support area, dots: contact corners)

10 cm (print at 100%, no "fit to page")