

move robot: +x -> assembly spot: -y
board x [-6.46, 22.24] cm, y [-1.41, 18.59] cm
blue: on the board (dashed: support area, dots: contact corners)
10 cm (print at 100%, no "fit to page")
4
move
5
move
tips at 17 deg: place carefully
1
hold
2
move
tips at 17 deg: place carefully
3
move
tips at 17 deg: place carefully
0
move
tips at 14 deg: place carefully
6
move
tips at 17 deg: place carefully