













tips at 18 deg: place carefully



tips at 18 deg: place carefully

move robot: +x -> assembly spot: -y
board x [-15.15, 13.55] cm, y [26.25, 46.25] cm
blue: on the board (dashed: support area, dots: contact corners)

10 cm (print at 100%, no "fit to page")