

5
move
tips at 18 deg: place carefully
2
move
1
move
0
move
tips at 18 deg: place carefully
3
hold
4
move
move robot: +x -> assembly spot: -y
board x [-14.50, 14.20] cm, y [21.22, 41.22] cm
blue: on the board (dashed: support area, dots: contact corners)
10 cm (print at 100%, no "fit to page")