





tips at 18 deg: place carefully





tips at 18 deg: place carefully



move robot: +x -> assembly spot: -y
board x [-11.70, 8.30] cm, y [2.03, 30.73] cm
blue: on the board (dashed: support area, dots: contact corners)

10 cm (print at 100%, no "fit to page")