






tips at 18 deg: place carefully







tips at 18 deg: place carefully



move robot: +x -> assembly spot: -y
board x [-23.80, 4.90] cm, y [23.75, 43.75] cm
blue: on the board (dashed: support area, dots: contact corners)

10 cm (print at 100%, no "fit to page")