








tips at 18 deg: place carefully




tips at 18 deg: place carefully




move robot: +x ->  assembly spot: -y
board x [-20.47, -0.47] cm, y [-6.25, 22.45] cm
blue: on the board (dashed: support area, dots: contact corners)

10 cm (print at 100%, no "fit to page")