









tips at 18 deg: place carefully



tips at 18 deg: place carefully





move robot: +x -> assembly spot: -y
board x [-13.90, 14.80] cm, y [-5.00, 15.00] cm
blue: on the board (dashed: support area, dots: contact corners)

10 cm (print at 100%, no "fit to page")