









tips at 18 deg: place carefully





tips at 18 deg: place carefully



move robot: +x -> assembly spot: -y
board x [-8.78, 11.22] cm, y [-11.15, 17.55] cm
blue: on the board (dashed: support area, dots: contact corners)

10 cm (print at 100%, no "fit to page")