









tips at 18 deg: place carefully







tips at 18 deg: place carefully

move robot: +x -> assembly spot: -y
board x [-18.75, 8.75] cm, y [-13.75, 6.25] cm
blue: on the board (dashed: support area, dots: contact corners)

10 cm (print at 100%, no "fit to page")