plotSingleSimulationAngle

Search for available trainings or test dataset and plot dataset. Follow user input dialog to choose which dataset and decide how many angles to plot. Plot single Angle and save figure to file. File name same as dataset with attach angle index.

Contents

- Syntax
- Description
- Examples
- Input Argurments
- Output Argurments
- Requirements
- See Also

Syntax

plotSingleSimulationAngle()

Description

plotSingleSimulationAngle() plot training or test dataset which are loacated in data/test or data/training. The function list all datasets and the user must decide during user input dialog which dataset to plot and which angle to visualize to. It loads path from config.mat and scans for file automatically.

Examples

plotSingleSimulationAngle()

Input Argurments

None

Output Argurments

None

Requirements

- Other m-files required: None
- Subfunctions: None
- MAT-files required: config.mat

See Also

- generateSimulationDatasets
- sensorArraySimulation
- generateConfigMat

Created on November 28. 2020 by Tobias Wulf. Copyright Tobias Wulf 2020.

```
TestDatasets = dir(fullfile(PathVariables.testDataPath, 'Test *.mat'));
   allDatasets = [TrainingDatasets; TestDatasets];
   % check if files available
   if isemptv(allDatasets)
      error('No training or test datasets found.');
catch ME
   rethrow(ME)
end
% number of datasets
nDatasets = length(allDatasets);
fprintf('Found %d datasets:\n', nDatasets)
for i = 1:nDatasets
   fprintf('%s\t:\t(%d)\n', allDatasets(i).name, i)
end
% get numeric user input to indicate which dataset to plot
iDataset = input('Type number to choose dataset to plot to: ');
% iDataset = 2;
ds = load(fullfile(allDatasets(iDataset).folder, ...
      allDatasets(iDataset).name));
   % check how many angles in dataset and let user decide how many to
   % render in polt
   fprintf('Detect %d angles ([1:%d]) in dataset ...\n', ..
      ds.Info.UseOptions.nAngles, ds.Info.UseOptions.nAngles);
   fprintf('Resolution\t:\t%.1f\n', ds.Info.UseOptions.angleRes);
   fprintf('Step width\t:\t%.1f\n', ds.Data.angleStep);
   fprintf('Start angle\t:\t%.1f\n', ds.Data.angles(1))
   idx = input('Which angle do you wish to plot (enter index): ');
   angle = interp1(ds.Data.angles, idx, 'nearest');
catch MF
   rethrow(ME)
fPath = fullfile(PathVariables.saveFiguresPath);
fSvgPath = fullfile(PathVariables.saveImagesPath, 'svg');
fEpsPath = fullfile(PathVariables.saveImagesPath, 'eps');
fPdfPath = fullfile(PathVariables.saveImagesPath, 'pdf');
fig = figure('Name', 'Sensor Array', ...
   'NumberTitle' , 'off', ...
   'WindowStyle', 'normal', ...
   'MenuBar', 'none', ...
'ToolBar', 'none', ...
'Units', 'centimeters',
   'OuterPosition', [0 0 30 30], ...
   'PaperType', 'a4', ...
'PaperUnits', 'centimeters', ...
   'PaperOrientation', 'landscape', ...
   'PaperPositionMode', 'auto', ...
'DoubleBuffer', 'on', ...
'RendererMode', 'manual', ...
   'Renderer', 'painters');
tdl = tiledlayout(fig, 2, 2, ...
   'Padding', 'normal', ..
   'TileSpacing' , 'compact');
title(tdl, 'Sensor Array Simulation', ...
```

```
'FontWeight', 'normal', ...
       'FontSize', 18, ...
       'FontName', 'Times', ...
       'Interpreter', 'latex');
   subline1 = "Sensor Array (%s) of $%d\\times%d$ sensors, an edge length of $%.1f$ mm,
a rel. pos. to magnet surface of";
   subline2 = " $(%.1f, %.1f, -(%.1f)) $ in mm, a magnet tilt of $%.1f^\circ$, a sphere
radius of $%.1f$ mm, a imprinted";
   subline3 = "field strength of $%.1f$ kA/m at $%.1f$ mm from sphere surface in z-axis,
$%d$ rotation angles with a ";
   subline4 = "step width of $%.1f^\\circ$ and a resolution of $%.1f^\\circ$. Visualized
is rotatation angle %d $(%.1f^\\circ)$.";
   subline5 = "Based on %s characterization reference %s.";
   sub = [sprintf(subline1, ...
                 ds.Info.SensorArrayOptions.geometry, ...
                 ds.Info.SensorArrayOptions.dimension, ...
                 ds.Info.SensorArrayOptions.dimension, ...
                 ds.Info.SensorArrayOptions.edge); ...
         sprintf(subline2, ...
                 ds.Info.UseOptions.xPos, ...
                 ds.Info.UseOptions.yPos, ...
                 ds.Info.UseOptions.zPos, ...
                 ds.Info.UseOptions.tilt, ...
                 ds.Info.DipoleOptions.sphereRadius); ...
         sprintf(subline3, ..
                 ds.Info.DipoleOptions.HOmag, ...
                 ds.Info.DipoleOptions.z0, ...
                 ds.Info.UseOptions.nAngles); ...
         sprintf(subline4, ...
                 ds.Data.angleStep, ...
                 ds.Info.UseOptions.angleRes, ...
                 idx, angle)
         sprintf(subline5, ..
                 ds.Info.CharData, ...
                 ds.Info.UseOptions.BridgeReference)];
   subtitle(tdl, sub, ...
       'FontWeight', 'normal', ...
       'FontSize', 14, ...
       'FontName', 'Times', ...
       'Interpreter', 'latex');
   N = ds.Info.SensorArrayOptions.dimension;
   X = ds.Data.X;
   Y = ds.Data.Y;
   Z = ds.Data.Z;
   % calc limits of plot 1
   maxX = ds.Info.UseOptions.xPos + ds.Info.SensorArrayOptions.edge;
   maxY = ds.Info.UseOptions.yPos + ds.Info.SensorArrayOptions.edge;
   minX = ds.Info.UseOptions.xPos - ds.Info.SensorArrayOptions.edge;
minY = ds.Info.UseOptions.yPos - ds.Info.SensorArrayOptions.edge;
   % calculate colormap to identify scatter points
   c=zeros(N,N,3);
   for i = 1:N
       for j = 1:N
          c(i,j,:) = [(2*N+1-2*i), (2*N+1-2*j), (i+j)]/2/N;
   end
   c = squeeze(reshape(c, N^2, 1, 3));
   % load offset voltage to subtract from cosinus, sinus voltage
   Voff = ds.Info.SensorArrayOptions.Voff;
   ax1 = nexttile(1);
```

```
% plot each cooredinate in loop to create a special shading constant
\ensuremath{\text{\%}} reliable to orientation for all matrice
hold on;
scatter(X(:), Y(:), [], c, 'filled', 'MarkerEdgeColor', 'k', ...
    'LineWidth', 0.8);
% axis shape and ticks
axis square xy;
axis tight;
grid on;
xlim([minX maxX]);
ylim([minY maxY]);
% text and labels
text(minX+0.2, minY+0.2, ...
    sprintf('$Z = %.1f$ mm', Z(1)), ...
    'Color', 'k', ...
    'FontSize', 16, ...
    'FontName', 'Times', ...
    'Interpreter', 'latex');
xlabel('$X$ in mm', ...
    'FontWeight', 'normal', ...
    'FontSize', 12, ...
    'FontName', 'Times', ...
    'Interpreter', 'latex');
ylabel('$Y$ in mm', ...
    'FontWeight', 'normal', ...
    'FontSize', 12, ...
    'FontName', 'Times',
    'Interpreter', 'latex');
title(sprintf('Sensor Array $%d\\times%d$', N, N), ...
    'FontWeight', 'normal', ...
    'FontSize', 12, ...
    'FontName', 'Times', ...
    'Interpreter', 'latex');
hold off;
nexttile(2);
\% plot all angles grayed out
polarscatter(ds.Data.angles/180*pi, ones(1, ds.Info.UseOptions.nAngles), ...
    [], [0.8 0.8 0.8], 'filled');
% radius ticks and label
rticks(1);
rticklabels("");
hold on;
% plot subset of angles
% polarscatter(subAngles/180*pi, ones(1, nSubAngles), 'k', 'LineWidth', 0.8);
ax2 = gca;
% axis shape
axis tight;
% text an labels
% init first rotation step label
tA = text(2/3*pi, 1.5, ...
    '$\\theta$', ...
    'Color', 'b', ...
    'FontSize', 16, ...
    'FontName', 'Times', ...
    'Interpreter', 'latex');
title('Rotation around Z-Axis in Degree', ...
    'FontWeight', 'normal', ...
```

```
'FontSize', 12, ...
    'FontName', 'Times', ...
    'Interpreter', 'latex');
hold off;
ax3 = nexttile(3);
hold on;
% set colormap
colormap('gray');
% plot cosinus reference, set NaN values to white color, orient Y to normal
imC = imagesc(ds.Data.HxScale, ds.Data.HyScale, ds.Data.VcosRef);
set(imC, 'AlphaData', ~isnan(ds.Data.VcosRef));
set(gca, 'YDir', 'normal')
% axis shape and ticks
axis square xy;
axis tight;
yticks(xticks);
grid on;
% test and labels
xlabel('$H_x$ in kA/m', ...
   'FontWeight', 'normal', ...
   'FontSize', 12, ...
'FontName', 'Times', ...
'Interpreter', 'latex');
ylabel('$H_y$ in kA/m', ...
    'FontWeight', 'normal', ...
   'FontSize', 12, ...
   'FontName', 'Times', ...
   'Interpreter', 'latex');
title('$V_{cos}(H_x, H_y)$', ...
   'FontWeight', 'normal', ...
'FontSize', 12, ...
   'FontName', 'Times', ...
   'Interpreter', 'latex');
% add colorbar and place it
cb1 = colorbar;
cbl.Label.String = sprintf(...

'$V_{cos}(H_x, H_y)$ in V, $V_{cc} = %1.1f$ V, $V_{off} = %1.2f$ V', ...
   ds.Info.SensorArrayOptions.Vcc, ds.Info.SensorArrayOptions.Voff);
cb1.Label.Interpreter = 'latex';
cb1.Label.FontSize = 12;
hold off:
ax4 = nexttile(4);
hold on;
% set colormap
colormap('gray');
% plot sinus reference, set NaN values to white color, orient Y to normal
imS = imagesc(ds.Data.HxScale, ds.Data.HyScale, ds.Data.VsinRef);
set(imS, 'AlphaData', ~isnan(ds.Data.VsinRef));
set(gca, 'YDir', 'normal')
% axis shape and ticks
axis square xy;
axis tight;
yticks(xticks);
```

```
grid on;
% test and labels
xlabel('$H_x$ in kA/m', ...
    'FontWeight', 'normal', ...
    'FontSize', 12, ...
    'FontName', 'Times', ...
'Interpreter', 'latex');
ylabel('$H_y$ in kA/m', ...
    'FontWeight', 'normal', ...
    'FontSize', 12, ...
    'FontName', 'Times', ...
'Interpreter', 'latex');
title('$V_{sin}(H_x, H_y)$', ...
    'FontWeight', 'normal', ...
    'FontSize', 12, ...
    'FontName', 'Times', ..
    'Interpreter', 'latex');
% add colorbar and place it
cb2 = colorbar;
cb2.Label.String = sprintf(...
    $^{sin}(H_x, H_y)$ in V, $V_{cc} = $1.1f$ V, $V_{off} = $1.2f$ V', ...
    ds.Info.SensorArrayOptions.Vcc, ds.Info.SensorArrayOptions.Voff);
cb2.Label.Interpreter = 'latex';
cb2.Label.FontSize = 12;
hold off;
nexttile(3);
ax5 = axes('Position', [0.07 0.02 0.19 0.19], 'XColor', 'r', 'YColor', 'r');
hold on;
axis square xy;
grid on;
hold off;
% H load subset
Hx = ds.Data.Hx(:,:,idx);
Hy = ds.Data.Hy(:,:,idx);
% get min max
maxHx = max(Hx, [], 'all');
maxHy = max(Hy, [], 'all');
minHx = min(Hx, [], 'all');
minHy = min(Hy, [], 'all');
dHx = abs(maxHx - minHx);
dHy = abs(maxHy - minHy);
% load V subset
Vcos = ds.Data.Vcos(:,:,idx) - Voff;
Vsin = ds.Data.Vsin(:,:,idx) - Voff;
angle = ds.Data.angles(idx);
% lock plots
hold(ax1, 'on');
hold(ax2, 'on');
hold(ax3, 'on');
hold(ax4, 'on');
hold(ax5, 'on');
% update plot 1
qH = quiver(ax1, X, Y, Hx, Hy, 0.5, 'b');
qV = quiver(ax1, X, Y, Vcos, Vsin, 0.5, 'r');
legend([qH qV], {'$quiver(H_x,H_y)$', '$quiver(V_{cos}-V_{off},V_{sin}-V_{off})$'},...
```

```
'FontWeight', 'normal', ...
         'FontSize', 9, ...
         'FontName', 'Times', ...
         'Interpreter', 'latex',
        'Location', 'NorthEast');
    % update plot 2
    tA.String = sprintf('$%.1f^\\circ$', angle);
polarscatter(ax2, angle/180*pi, 1, 'b', 'filled', ...
         'MarkerEdgeColor', 'k', 'LineWidth', 0.8);
    % update plot 3 and 4
    scatter(ax3, Hx(:), Hy(:), 5, c, 'filled', 'MarkerEdgeColor', 'k', ...
         'LineWidth', 0.8);
    scatter(ax4, Hx(:), Hy(:), 5, c, 'filled', 'MarkerEdgeColor', 'k', ...
         'LineWidth', 0.8);
    % calc position of scatter area frame and reframe
    pos = [minHx - 0.3 * dHx, minHy - 0.3 * dHy, 1.6 * dHx, 1.6 * dHy];
    rectangle(ax3, 'Position', pos, 'LineWidth', 1, 'EdgeColor', 'r');
rectangle(ax4, 'Position', pos, 'LineWidth', 1, 'EdgeColor', 'r');
    % update plot 5 (zoom)
    scatter(ax5, Hx(:), Hy(:), [], c, 'filled', 'MarkerEdgeColor', 'k', ...
         'LineWidth', 0.8);
    xlim(ax5, [pos(1) maxHx + 0.3 * dHx])
    ylim(ax5, [pos(2) maxHy + 0.3 * dHy])
    % release plots
   * retease ptots
hold(ax1, 'off');
hold(ax2, 'off');
hold(ax3, 'off');
hold(ax4, 'off');
hold(ax5, 'off');
    % get file path to save figure with angle index
    [~, fName, ~] = fileparts(ds.Info.filePath);
    \% save to various formats
    yesno = input('Save? [y/n]: ', 's');
    if strcmp(yesno, 'y')
        fLabel = input('Enter file label: ', 's');
        fName = fName + sprintf("_AnglePlot_%d_", idx) + fLabel;
        savefig(fig, fullfile(fPath, fName));
        print(fig, fullfile(fSvgPath, fName), '-dsvg');
print(fig, fullfile(fEpsPath, fName), '-depsc', '-tiff', '-loose');
print(fig, fullfile(fPdfPath, fName), '-dpdf', '-loose', '-fillpage');
    end
    close(fig);
end
```