Land Transport Authority ITSO Division	Division/Section: ITSO Division /ITSO OCC Traffic Operations Document No: ITSO/OCC/SOP/EOP04.002	Rev No. 2 Effective Date: Xx Dec 2020
ITSC	D & Facilities Buildings Fire)

Doc No.	ITSO/OCC/SOP/EOP04.002	Page	1 of 22
File	ITSO & Facilities Buildings Fire		

ITSO & Facilities Buildings Fire

Table of Contents

1	INTRODUCTION	5
2	PERSONNEL INVOLVED	5
	ACTION&PROCESS	
4	ABBREVIATIONS	7
5	ATTACHMENTS	3-22

Doc No.	ITSO/OCC/SOP/EOP04.002	Page	2 of 22
File	ITSO & Facilities Buildings Fire		

ITSO & Facilities Buildings Fire

DOCUMENT CONTROL

REV	DOCUMENT TITLE & COPY NUMBER	Date	Prepared by	Reviewed by	Approved by
0	ITSO & Facilities Buildings Fire Copyof	15 th December 2009	Muhamad Ridha (OE)	Alfred Loh (SOE)	Soh Ling Tim (MOPN)
1	ITSO & Facilities Buildings Fire Copyof	XX October 2013	Chiam Zhi Wei (DysOE) Chua Teck Leong (AOM, ITSO OCC)	Ng Soon Han, Frankie (DOM, ITSO OCC)	Yeo Se Lay (SM,Ops)
2	ITSO & Facilities Buildings Fire Copyof	XX December 2020	Daniel Wu (AOM) Lye Keng Fatt (DM, ITSO OCC)	Ng Soon Han, Frankie (Mgr, ITSO OCC)	Yeo Se Lay (DDIT)

Doc No.	ITSO/OCC/SOP/EOP04.002	Page	3 of 22
File	ITSO & Facilities Buildings Fire		

ITSO & Facilities Buildings Fire

AMENDMENT HISTORY RECORD

Rev	Effective	Section & Sub-	Amendments/ References	Party Requesting
1:.	Date of	Section		for Change
No.	Change	Amended		
1	XX Oct	Whole	Due to organization change of division	DOM, ITSO OCC
	2013	Document	name from ITSO to ITSO.	
2	XX Dec	Whole	Due to change of Staff Designations in	Mgr, ITSO OCC
	2020	Document	ITSO OCC.	
			Delete SOE, insert DM	
			Delete DySOE, insert DyAM	

Doc No.	ITSO/OCC/SOP/EOP04.002	Page	4 of 22
File	ITSO & Facilities Buildings Fire		

ITSO & Facilities Buildings Fire

Section 1. Introduction

- 1.1.1 This document describes the handling process for fire incident occurrence in both the ITSO building and the tunnel facility buildings.
- 1.1.2 The tunnel facility buildings are normally unoccupied buildings housing mainly tunnel equipment and power distribution facility for tunnel. Maintenance personnel doing corrective or preventive maintenance work may at times occupy these facility buildings. These personnel are required to give ITSO OCC a contact number so that they can be contacted in times of emergency.
- 1.1.3 As for ITSO building, it is the nerve center for daily Singapore road operations. It houses all the equipment essential to perform this task, it also houses the OCC and all the related ITSO department. For any fire incident there is a need to evacuate all the personnel from the building.

Section 2. Personnel Involved

- a) ITSO OCC staff
- b) LTM & VRS staff
- c) Other ITSO department staff
- d) External Agencies

Section 3. Actions & Process

Sub-Section 3.1 ITSO Building Fire Incidents

- 3.1.1 Should any member of staff upon discovering a fire or signs of a fire, will carry out the following steps:
 - a. Raise the alarm by operating the nearest break-glass (refer to Attachment 1 for location) to sound alarm and calling ITSO OCC.
 - b. try to extinguish fire if possible using the appliances provided.
 - c. If the fire is uncontrollable do not take risks, leave the area immediately.
- 3.1.2 The operation of the break-glass unit initiates the Fire Alarm Bells, which will ring continuously.
- 3.1.3 All ITSO staff and any persons within ITSO building on hearing the continuous ringing of the Fire Alarm Bells must evacuate the building immediately, by the safest Exit (refer to Attachment 3), and proceed to the Assembly Point in front of the building. Staff must ensure that they close all doors behind them.
- 3.1.4 The persons responsible for evacuation of their particular area must ensure that no one is left behind in their area of responsibility (Refer to Attachment 3 for name list of persons with area evacuation responsibility).
- 3.1.5 In the event of fire, the ITSO security shall ensure no person(s) or vehicles except for SCDF enter or re-enter the building.
- 3.1.6 On arrival of SCDF personnel, the DM shall liaise with the SCDF officer-in-charge of the incident.

Doc No.	ITSO/OCC/SOP/EOP04.002	Page	5 of 22
File	ITSO & Facilities Buildings Fire		

ITSO & Facilities Buildings Fire

3.1.7 The staff to remain outside the Control Building until the SCDF Officer confirms it is safe to reenter

Sub-Section 3.2 ITSO Building Fire Incident (Actions by ITSO OCC Staff)

- 3.2.1 If the fire alarm is detected from the Fire System Main Terminal in the Control room, OCC staff will acknowledge the alarm quickly and off the buzzer.
- 3.2.2 Check fire alarm location. If the alarm location is in ITSO Building, one member of the OCC staff should proceed straight to the scene with the walkie-talkie, Telecom room key, Communication room key, Hydrant Cabinet key and Halon/FM200 Control Panel Key. The others will remain and carry on with the operations in the Control Centre.
- 3.2.3 After checking the location if the alarm is false, reset the alarm (Refer to ITSO/OCC/WM/SYS03.011for fire alarm Panel reset). If after reset the alarm occurs again do a check of alarm location. Reset fire alarm again if it is false and report to the maintenance contractor.
- 3.2.4 If the fire alarm location is in the following rooms:
 - a) 2nd storey: Telecom Room, Communication Room, Computer Room and Control Room
 - b) 3rd storey: TrafficScan Room, Transport Information (TI) Hub room and GLIDE Meeting Room (former GLIDE Computer Room),

OE shall take action to block the gas discharge (Halon or FM 200) and reset the control panel if there is a false alarm (Refer to ITSO/OCC/WM/SYS03.011 for Halon or FM200 Panel reset).

- 3.2.5 Upon confirming fire is real and if the fire is small, use the fire extinguisher or hose reel to extinguish it.
- 3.2.6 If fire is uncontrollable or becomes uncontrollable, inform the DM in the Control room to seek help from SCDF and Police. If the room belongs to those mentioned in 3.2.4 smash the break-glass and operate the manual release switch at the Halon/FM200 Control Panel to discharge the gas.
- 3.2.7 OE at fire site shall also activate the manual call point to raise the alarm for ITSO building evacuation.
- 3.2.8 DM shall call SCDF and Police for help and inform the Operations Manager and escalate to higher management.
- 3.2.9 If fire is in OCC or its immediate vicinity threatening the OCC, all operation staff must log out of their system and evacuate the OCC and leave the building immediately by the nearest safest exit to the Assembly point.
- 3.2.10 All operation staff should take the mobi-talk with them and DM will take the duty handphone and ensure the all staff in OCC has been evacuated and escalate to higher management via duty handphone (Refer to Attachment 6).

Doc No.	ITSO/OCC/SOP/EOP04.002	Page	6 of 22
File	ITSO & Facilities Buildings Fire		

ITSO & Facilities Buildings Fire

Sub-Section 3.3 Facilities Building Fire(FBs) Incident.

- 3.3.1 Upon notification of a fire via the FB fire alarm system or reports from public, use J-eyes (if possible) and send RC and LTM to reported area to investigate.
- 3.3.2 If the fire notification is confirmed false, DM will acknowledge the fire alarm immediately and put off the buzzer if it is via the fire alarm panel, if it is via public calls take no further action and treat as a hoax.
- 3.3.3 The Tunnel OE will notify the Maintenance Team if alarm is confirmed false.
- 3.3.4 If the fire alarm is confirmed real (or a fire report is received by contractors in the FB), RC shall try to extinguish the fire if possible, if fire is uncontrollable, DM shall call SCDF, Police and escalate to higher management immediately (Refer to Attachment 6). LTM shall wait at the main gate of the FB to direct the attention of the emergency services.
- 3.3.5 LTM and RC shall assist the emergency services to cordon off the affected FB.
- 3.3.6 Tunnel OE shall contact any contractors who are known to be working in the incident FB (for cases where the fire is not reported by contractors) to evacuate immediately. Tunnel OE will also monitor and confirm if any tunnel equipment function is affected by the FB fire.
- 3.3.7 If any of the lighting, LUS or any equipment needed for safe tunnel driving is affected, tunnel OE shall take the appropriate steps to warn motorist.

Section 4. Abbreviations

CMG Crisis Management Group

EMAS Expressway Monitoring Advisory Service

ITSO Intelligent Transport Systems Operations

LTA Land Transport Authority

LTM Land Transport Authority Traffic Marshals

OE Operations Executive

OCC Operations Control Center

PTZ Pan Tilt Zoom Camera

PUB Public Utilities Board

RC Recovery Crew

DM Deputy Manager

SPF Singapore Police Force

SCDF Singapore Civil Defense Force

TM Traffic Management

TP Traffic Police

VRS Vehicle Recovery Service VMS Variable Message Signs

Doc No.	ITSO/OCC/SOP/EOP04.002	Page	7 of 22
File	ITSO & Facilities Buildings Fire		

ITSO & Facilities Buildings Fire

ATTACHMENT 1- THE FIRE ALARM MANUAL CALLPOINT (BREAK-GLASS) LOCATIONS

BASEMENT CARPARK

Carpark (near electrical riser)
Carpark (near fuel tank)
Carpark (near intake shaft)
Sprinkler Pump Room

FIRST STOREY

Lift Lobby
Driveway (near Bin Centre)
Driveway Ramp (at LV cable chamber)
Corridor (near HV Switchroom)
Corridor (leading to Staircase 3)
Parking bay beside Genset room

SECOND STOREY

Lift Lobby
Corridor (near Halon Room leading to Staircase 1)
Corridor (leading to Staircase 3)
Corridor (next to Day Room)

THIRD STOREY

Lift Lobby
Corridor (near Janitor Storeroom leading to Staircase 1)
Corridor (leading to Staircase 3)

FOURTH STOREY


Lift Lobby Fan Motor Room

Doc No.	ITSO/OCC/SOP/EOP04.002	Page	8 of 22
File	ITSO & Facilities Buildings Fire		

ITSO & Facilities Buildings Fire

ATTACHMENT 2 -ESCAPE EXIT LOCATION

A2a) Basement Carpark Exits Use driveway or emergency staircase 1 to River Valley Road




BASEMENT FLOOR PLAN

Doc No.	ITSO/OCC/SOP/EOP04.002	Page	9 of 22
File	ITSO & Facilities Buildings Fire		

ITSO & Facilities Buildings Fire

A2b) First Storey Exits

Use main entrance or driveway to car park




1ST STOREY PLAN

Doc No.	ITSO/OCC/SOP/EOP04.002	Page	10 of 22
File	ITSO & Facilities Buildings Fire		


ITSO & Facilities Buildings Fire

A2c) Second Storey Exits Use emergency staircase 1 to River Valley Road (front of building) emergency staircase 2 to Lift Lobby (front of building) emergency staircase 3 to Clemenceau Ave, (back of building).



2ND STOREY PLAN


Doc No.	ITSO/OCC/SOP/EOP04.002	Page	11 of 22
File	ITSO & Facilities Buildings Fire		



3RD STOREY PLAN

Doc No.	ITSO/OCC/SOP/EOP04.002	Page	12 of 22
File	ITSO & Facilities Buildings Fire		

A2 e) Fourth Storey Exits



4TH STOREY PLAN

Doc No.	ITSO/OCC/SOP/EOP04.002	Page	13 of 22
File	ITSO & Facilities Buildings Fire		

ITSO & Facilities Buildings Fire

ATTACHMENT 3

LIST OF PERSONS RESPONSIBLE FOR THE EVACUATING THEIR RESPECTIVE AREAS & FIRE ALARM HANDLING FLOW-CHART

A3a) List of Person in charge:

i) Level 1/Visitors - Fire Wardens: Ithnin, Ng Bee Chin, Lim Soon Peng


ii) Level 2 - Fire Wardens: Mary Tan, Low Thaim Teck, Wil Liam Tan

iii) Level 3 - Fire Wardens: Louis Ang, Rohana, Alfie, Dominic Tay (Ti-Hub rm)


iv) Level 4 - Fire Wardens: Wu Gang, Wong Teck Khuan, Lim Yong Kiat

INTENTIONALLY LEFT BLANK

Doc No.	ITSO/OCC/SOP/EOP04.002	Page	14 of 22
File	ITSO & Facilities Buildings Fire		




Doc No.	ITSO/OCC/SOP/EOP04.002	Page	15 of 22
File	ITSO & Facilities Buildings Fire		




A4a) LOCATION OF FACILITIES BUILDING NO 01 (FB 01) BUKIT TIMAH ROAD

Doc No.	ITSO/OCC/SOP/EOP04.002	Page	16 of 22
File	ITSO & Facilities Buildings Fire		




A4b) LOCATION OF FACILITIES BUILDING NO 02 (FB 02) CLEMENCEAU AVE NORTH

Doc No.	ITSO/OCC/SOP/EOP04.002	Page	17 of 22
File	ITSO & Facilities Buildings Fire		




A4c) LOCATION OF FACILITIES BUILDING NO 03 (FB 03) KRAMAT ROAD

Doc No.	ITSO/OCC/SOP/EOP04.002	Page	18 of 22
File	ITSO & Facilities Buildings Fire		



A4d) LOCATION OF FACILITIES BUILDING NO 04 (FB 04) PEARL'S HILL ROAD

Doc No.	ITSO/OCC/SOP/EOP04.002	Page	19 of 22
File	ITSO & Facilities Buildings Fire		




A4e) Location of ITSO Building- Intelligent Transport
Systems Centre
Land Transport Authority
181 River Valley Road
Singapore 179034

Doc No.	ITSO/OCC/SOP/EOP04.002	Page	20 of 22
File	ITSO & Facilities Buildings Fire		

ITSO & Facilities Buildings Fire


ATTACHMENT 5- FCT FACILITIES BUILDING LOCATION



Doc No.	ITSO/OCC/SOP/EOP04.002	Page	21 of 22
File	ITSO & Facilities Buildings Fire		

ATTACHMENT 6

ESCALATION OF INFORMATION ON INCIDENTS



¹To exclude those who are on leave

²Some examples of Unusual Incidents:

- (a) Abnormal massive jam on arterial roads
- (b) Huge obstacles such as fallen trees (affecting > 50% of carriageway)
- (c) Road cave-in
- (d) Serious upheaval of road surface
- (e) Flooding
- (f) Serious road settlement, subsidence or undulating carriageway over a considerable length of road
- (g) Unauthorised works on roads that adversely affect traffic flow / unusual events on roads
- (h) Severe damage to overhead gantry/cantilever sign causing massive jam or posing safety hazard (Also to inform DM (Fac Mgmt) & M (Mgmt) if it is an EMAS sign)

³Disaster - Please refer to the LTA CMG Minor Disaster List

⁴For Tunnel fire, SCDF takes command and control of the rescue and recovery operations

Doc No.	ITSO/OCC/SOP/EOP04.002	Page	22 of 22
File	ITSO & Facilities Buildings Fire		

SMS Message

(a) Est. Nos. of SMS per incident: (i) Start of an incident (ii) updates when there is a change in status (iii) End of an incident.

(b) Format: <Time>: <New or U/D>: <Type of incident>: <Location>: <Actions taken>: <Impact of incident> E.g. 0650hrs: New – Accident CTE(AYE) aft PIE(Changi) on Ln 1. TP & TW informed. Congestion 4km up to AMK Ave 1